


## CERTIFICATE.

The inspection of School Building of Shivalik Public School, Gangath, Tehsil Indora, Distt. Kangra (HP) has been conducted by the Assistant Engineer, Sub Division, HP. PWD. Indora accompanied with Junior Engineer. On the basis of their inspection report, it has been reported that no Earthquakes resistant norms have been adopted for the construction of School Building. No structural drawings approved by the competent Govt. agency were produced <sup>by</sup> the School authority. The structure of the building is a non Engineering structure. Hence, the structural safety of building can't be ensured specially from Earthquake point of view. This Department will not responsible for any type of loss of life and property etc. if this structure fails under any circumstances.

However, as per visual inspection, the building appears to be safe and accordingly, the School Building Safety Certificate is being issued by this Department from 01.04.2023 to 31.03.2024. This Department could not access the structural safety of said building as the same was not constructed under the supervision of this Department.

  
Executive Engineer,  
Indora Division, HP.PWD.  
Indora.



HIMACHAL PRADESH  
PUBLIC WORKS DEPARTMENT

No. PWN/CB/WA/School Building/2022-23/- 10998-99  
To


Dated:- 24-3-2023

✓ The Manager,  
Shivalik Public School Gangath,  
Tehsil. Indora,  
Distt. Kangra (HP).

Subject: - Application regarding requisite of Building Safety Certificate.

With reference to your office application No. SPS/ Building Certificate/2023-23-054 dated 06.02.2023, the School building Certificate of your School is being sent for information and further action.

DA/ As above.

  
Executive Engineer,  
Indora Division, HP.PWD.  
Indora.

Copy to the Assistant Engineer, Sub Division, HP.PWD. Indora for information w.r.t. his office Letter No. 1870 dated 06.03.2023.

✓  
Executive Engineer,  
Indora Division, HP.PWD.  
Indora.